

Shining® Cart Cleaning Checklist

Use cavicide wipes to clean:

- Cart surfaces touched during the procedure
- Keyboard
- Scanner wand and cord (replace dust cap after cleaning)
- Monitor (turn off the monitor first to prevent accidental clicking)

Bag and sterilize scan tip